




К 1




К 2




К 3




К 4




К 5




К 6




К 7




К 7/1




К 8




К 9




К 10




К 11




К 12




К 13




К 14




К 15




К 16




К 17




К 18




К 19




К 20




К 21




К 22




К 23




К 24



К 25



К 26



К 27


основные фрезы
М(9/2,5) Т(30/5)

дополнительные фрезы
МТ(13/2) S(25/6) ST(35/6)


К2,К10,К15-К19,
К22-К27
только фреза М




для ХДФ толщиной 4мм используются фрезы М и МТ, для МДФ толщиной 6мм - фрезы М и Т, для МДФ 10 мм и более - фрезы М, Т, S, ST




К 28




К 29




К 31




К 32




К 33




К 34




К 35




К 36




К 37




К 38




К 39




К 40




К 41




К 42




К 43




К 44




К 45




К 46




К 47




К 48




К 49




К 50




К 51




К 52




К 53



К 54



К 55




К 56

основные фрезы
М(9/2,5) Т(30/5)


дополнительные фрезы
МТ(13/2) S(25/6) ST(35/6)

К37, К43, К44,
К46, К47, К50-К56
только фреза М







К 57




К 58




К 59




К 60




К 61




К 62




К 63




К 64




К 65




К 66




К 67




К 68




К 69




К 70




К 71




К 72




К 73




К 74




К 75




К 76




К 77




К 78




К 79




К 80




К 81



К 82



К 83




К 84

основные фрезы
М(9/2,5) Т(30/5)


дополнительные фрезы
МТ(13/2) S(25/6) ST(35/6)

К58, К62, К63,
К64-К79, К82, К83
только фреза М







К 85




К 86




К 87




К 88




К 89




К 90




К 91




К 92




К 93




К 94




К 95




К 96




К 97




К 98




К 99




К 100




К 101




К 102




К 103




К 104




К 105




К 106




К 107




К 108




К 109



К 110



К 111



К 112

основные фрезы
М(9/2,5) Т(30/5)

дополнительные фрезы
МТ(13/2) S(25/6) ST(35/6)

К87, К92,
К111, К112
только фреза М

