




для ХДФ толщиной 4мм используются фрезы М и МТ, для МДФ толщиной 6мм - фрезы М и Т, для МДФ 10 мм и более - фрезы М, Т, S, ST




H 1




H 2




H 3




H 4




H 5




H 6




H 7




H 8




H 9




H 10




H 11




H 12




H 13




H 14




H 15




H 16




H 17




H 18




H 19




H 20




H 21




H 22




H 23




H 24




H 25



H 26



H 27




H 28

основные фрезы  
M(9/2,5) T(30/5)


дополнительные фрезы  
MT(13/2) S(25/6) ST(35/6)

H5, H6, H7, H8, H9,  
H13, H23, H28  
только фреза M







H 29




H 30




H 31




H 32




H 33




H 34




H 35




H 36




H 37




H 38




H 39




H 40




H 41




H 42




H 43




H 44




H 45




H 46




H 47




H 48




H 49




H 50




H 51




H 52




H 53



H 54



H 55




H 56


основные фрезы  
M(9/2,5) T(30/5)

дополнительные фрезы  
MT(13/2) S(25/6) ST(35/6)







H 57




H 58




H 59




H 60




H 61




H 62




H 63




H 64




H 65




H 66




H 67




H 68




H 69




H 70




H 71




H 72




H 73




H 74




H 75




H 76




H 77




H 78




H 79




H 80




H 81



H 82



H 83



H 84


основные фрезы  
M(9/2,5) T(30/5)

дополнительные фрезы  
MT(13/2) S(25/6) ST(35/6)


H57, H66, H69,  
H70, H84

только фреза M







H 85




H 86




H 87




H 88




H 89




H 90




H 91




H 92




H 93




H 94




H 95




H 96




H 97




H 98




H 99




H 100




H 101




H 102




H 103




H 104




H 105




H 106




H 107




H 108




H 109



H 110



H 111




H 112

основные фрезы  
M(9/2,5) T(30/5)


дополнительные фрезы  
MT(13/2) S(25/6) ST(35/6)

H105, H108, H111  
только фреза M







H 113




H 114




H 115




H 116




H 117




H 118




H 119




H 120




H 121




H 122




H 123




H 124




H 125




H 126




H 127




H 128




H 129




H 130




H 131




H 132




H 133




H 134




H 135




H 136




H 137



H 138



H 139




H 140

основные фрезы  
M(9/2,5) T(30/5)


дополнительные фрезы  
MT(13/2) S(25/6) ST(35/6)

H134, H137, H138  
только фреза M







H 141




H 142




H 143




H 144




H 145




H 146




H 147




H 148




H 149




H 150




H 151




H 152




H 153







H 154



H 155



H 156



основные фрезы  
M(9/2,5) T(30/5)

дополнительные фрезы  
MT(13/2) S(25/6) ST(35/6)

H151  
только фреза M

