




R 1




R 2




R 3




R 4




R 5




R 6




R 7




R 8




R 9




R 10




R 11




R 12




R 13




R 14




R 15




R 16




R 17




R 18




R 19




R 20




R 21




R 22




R 23




R 24




R 25



R 26



R 27




R 28

основные фрезы
M(9/2,5) T(30/5)


дополнительные фрезы
MT(13/2) S(25/6) ST(35/6)

R10-28
только фреза M







R 29




R 30




R 31




R 32




R 33




R 34




R 35




R 36




R 37




R 38




R 39




R 40




R 41



R 42




R 43




R 44




R 45




R 46



R 47




R 48




R 49




R 50




R 51




R 52




R 53



R 54



R 55




R 56

основные фрезы
M(9/2,5) T(30/5)


дополнительные фрезы
MT(13/2) S(25/6) ST(35/6)

R29-56
только фреза M







R 57




R 58




R 59




R 60




R 61




R 62




R 63




R 64




R 65




R 66




R 67




R 68




R 69




R 70




R 71




R 72




R 73




R 74




R 75




R 76




R 77




R 78




R 79




R 80




R 81



R 82



R 83





R 84

основные фрезы
M(9/2,5) T(30/5)


дополнительные фрезы
MT(13/2) S(25/6) ST(35/6)

R57-65,69-73,80
только фреза M







R 111




R 114




R 116




R 120




R 124




R 126




R 127




R 128




R 133




R 150




R 157




R 163




R 166




R 168




R 169




R 191




R 300




R 301




R 302






R 303



R 304



R 305



основные фрезы
M(9/2,5) T(30/5)

дополнительные фрезы
MT(13/2) S(25/6) ST(35/6)

R116,R126,R168,
R302

только фреза M

